



MarkVision Professional 11.2.1

Service Pack Plug-In version 1.0

Release Notes

February 2010

OVERVIEW

The MarkVision TM Professional (MVP) 11.2.1 Service Pack Plug-In is being released to fix issues related to manage certain printer settings (list below) for the following advanced security protected devices while communicating from Markvision through secure channel.

Advanced security protected devices

- C734, C736
- E460dn, E460dw, E462dtn
- T650, T652, T654, T656
- W850
- X463de, X464de, X466de, X466dte, X466dtwe
- X651de, X652de, X654de, X656de, X658de
- X734de, X736de, X738de
- X860de, X862de, X864de

List of Printer Settings

- Settings -> Printer -> General Settings
- Settings -> Printer -> Displayed Information
- Settings -> Printer -> Email Alert Setup
- Settings -> Printer -> Finishing/ Quality
- Settings -> Printer -> HTML
- Settings -> Printer -> Image
- Settings -> Printer -> IPDS
- Settings -> Printer -> Output Bin Names
- Settings -> Printer -> PCL
- Settings -> Printer -> PDF
- Settings -> Printer -> PostScript
- Settings -> Printer -> PPDS
- Settings -> Printer -> Printable Margins
- Settings -> Printer -> Supply Notifications
- Settings -> Printer -> XPS
- Settings -> Printer -> Paper
- Settings -> Printer -> Ports

Note: This is also true if these setting are being managed using device policy.

INSTALLATION

Note: You will need to remove all discovered devices from the MarkVision Server before installing the plug-in and perform a complete discovery after installing it. Please ensure any Discovery Profiles are up-to-date before removing devices.

1. Download the plug-in from <http://www.markvisionprofessional.com>.
2. In MarkVision Professional, remove all devices from the server (you will need to perform a complete rediscovery of all devices).
3. Select the *MarkVision* → *Software Update (Manage Plug-Ins)* task.
4. Select *Install New. . .* and browse to the directory where the downloaded plug-in(s) were saved. (Make sure *MVP Plug-in Files* is selected in the *Files of Type* drop-down list.)
5. Select the plug-in and select *Install Plug-In*.
6. You will need to exit MarkVision and restart the MarkVision Server and MarkVision.
7. Rediscover your devices.

Lexmark and Lexmark with diamond design are trademarks of Lexmark International, Inc., registered in the United States and/or other countries.

Other trademarks are the property of their respective owners.

© 2010 Lexmark International, Inc. All rights reserved.